

# National Council on Radiation Protection and Measurements

7910 Woodmont Avenue, Suite 400, Bethesda, Maryland 20814-3095

Voice (301) 657-2652 Ext. 25 • Fax (301) 907-8768 • <http://NCRPonline.org>

## MEMORANDUM

**Date:** May 20, 2019

**To:** NCRP Customers

**From:** Laura J. Atwell  
Director of Operations

**Subject:** Errata for NCRP Report No. 179

---

The following corrections should be made to NCRP Report No. 179, *Guidance for Emergency Response Dosimetry*:

- Table 4.2, page 31, “Personal emergency radiation detectors (PERDs) and monitors” row, third column, “**Limitations**” should be changed:

**from** “...effective dose-rate range down to 1 mR h<sup>-1</sup> (~1 μGy h<sup>-1</sup>) ... “

**to** “...effective dose-rate range down to 1 mR h<sup>-1</sup> (10 μGy h<sup>-1</sup>) ...”

These changes do not affect the recommendations and conclusions of this Report.